

Photos 1 & 2: Unpermitted stone wall constructed along bank (8.10.20).



45 Lakeview Avenue, Lynnfield, MA Amendment/Bank and Buffer Zone Restoration Plan

Site Photographs



Photos 3 & 4 : Previous bank condition prior to wall construction(2019).



45 Lakeview Avenue, Lynnfield, MA Amendment/ Bank and Buffer Zone Restoration Plan



Photos 5: Area 8-feet upgradient Bank to be restored with natural vegetation (8.10.20).

Photos 6: Newly reconstructed house and deck from the rear of the house facing pond side (8.10.20).



45 Lakeview Avenue, Lynnfield, MA Amendment/Bank and Buffer Zone Restoration Plan



Photos 7: Original bank condition with large stones (8.10.20).



Photos 8: Rear of house facing pond. 8-foot Buffer Zone to be planed off pond banks (8.10.20).

> 45 Lakeview Avenue, Lynnfield, MA Amendment/Bank and Buffer Zone Restoration Plan

Site Photographs



Photos 9 & 10: New subsurface sewage disposal system to be located in front of the house. Garage to be removed (8.10.20).



45 Lakeview Avenue, Lynnfield, MA Amendment/Bank and Buffer Zone Restoration Plan Sheet 5

Site Photographs