

Windsor Estates Strom Water Roof Run-off

Test Port #	Date Inspected	Water Visible (Yes/No)	Comments
1	7/28/2021	No	
2	7/28/2021	No	
3	7/28/2021	No	
4	7/28/2021	No	
5	7/28/2021	No	
6	7/28/2021	No	
7	7/28/2021	No	
8	7/28/2021	Yes	Significant amount of water
9	7/28/2021	Yes	Very bottom of Catch Basin
10	7/28/2021	No	
11	7/28/2021	Yes	A little standing water at very bottom
12	7/28/2021	No	
13	7/28/2021	Yes	Tes port is full of water
14	7/28/2021	No	
15	7/28/2021	Yes	A little standing water at very bottom
16	7/28/2021	No	
17	7/28/2021	No	

Date Inspected	Water Visible (Yes/No)	Comments	Date Inspected
8/6/2021	No		8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	Yes	Half full	8/11/2021
8/6/2021	Yes	Very bottom of Catch Basin	8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	Yes	A little standing water at very bottom	8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	Yes	Tes port is full of water	8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	Yes	Half full	8/11/2021
8/6/2021	No		8/11/2021
8/6/2021	No		8/11/2021

Water Visible (Yes/No)	Description
No	Front Entrance - Left side
No	Front Entrance - Right Side near 1st visitor parking
No	Front of Unit 3 - acrosss the street
No	Right side of Unit 1
No	Left of Unit 6
No	Behind Unit 44
No	Between Units 8 & 9
Yes - half full	Manhole grate between Units 11 & 13
No	Front of Unit 10
No	Left side of Unit 16
No	Behind Unit 22
No	Behind Unit 28
Yes - half full	Behind Unit 35
No	Behind Unit 38 - Rubber cap bolted onto port
Yes - 3/4 full	Left side of Unit 38
Yes - full	Two manhole grates behind Units 42 & 43
No	Between back of Units 41 & 42 - Also a manhole grate behind