



Photo 1 : 2-foot area of patio to be removed and planted against retaining wall (6.17.22).

Photo 2: Area of wall required to be removed to save tree. Recommend additional buffer zone plantings in this area (6.17.22).





Photo 3: Proposed 600 s.f. buffer zone mitigation area (6.17.22).

Photo 4: Invasive bittersweet along pond banks (6.17.22).

