

Photo 1: View of BVW northwest of the house (8.28.21).

Photo 2: Upland manicured lawn west of driveway upgradient BVW (8.28.21).





Photo 3: View of BVW east of the house along property line (8.28.21).

Photo 4: View of the front of the house, new system to be located west of the driveway (8.28.21).

